



2014 Greg Street
Suite 112
Azle, Texas 76020
(817) 444-5310
www.emagair.com

Mandatory Service Bulletin

Date: 12/1/23

Topic: Possible insufficient torque of sense-arm assembly screw.

Models Affected: 200-6XC (ignitions for Continental™ style engines). Thirteen (13) ignitions with serial numbers listed below.

Urgency: High



Identification: 200-6XC ignitions with the following serial numbers:
0832, 0833, 0834, 0835, 0857, 0855, 0856, 0857,
0858, 0992, 0993, 1019, 1020

Background:

A small batch of nose assemblies for 200-6XC ignitions may have insufficient torque applied to the internal sense-arm assembly screw. If this screw loosens, ignition operation could become inconsistent, rough, loose timing, or stop operating. Parts affected are internal to the ignition body.

Actions Required:

Return to E-MAG for correction (no cost to customer).